<u>VEHICLE</u>	VEHICLE NUMBER	MILEAGE	<u>VIN</u>	INSPECTION STATUS	REPAIRS REQUIRED	
1997 Chevy 2500 Pickup w/ Cap	501	80,500	1GCGK24F1VE148574	WILL NOT PASS INSPECTION	Rust - frame rot, bumpers, brake lines springs/hangers, oil leak, fuel leak, exhaust, shocks	
1997 Ford F250 Pickup w/Utility Bed	512	125,435	3FEHF36G7VMA64779	WILL NOT PASS INSPECTION	Rust - trans cooler lines & pan, fuel lines, intake manifold leaks coolant, battery, rear main seal, oil pan leak, front crank seal, exhaust	
1997 Ford F800 Dump Truck	510	50,380	1FDXF80E5VVA33220	WILL NOT PASS INSPECTION	Rust - cab mounts, dump bed, fuel tank & hangers, frame rot, air tanks leak, brake lining cracked, radiator, trans seal, shocks, battery box, exhaust, lift cylinder, tires, coolant lines	
1997 Ford F350 Dump Truck w/ Plow	544	44,370	1FDKF38F0VEA98373	WILL NOT PASS INSPECTION	Rust - fuel tank & straps, frame rot, cross members under cab, oil pan,	



dump body rot, dump body mounts, brakes lines, shocks, wiring issues, rotors, calipers, pads, wheel seals, drums, shoes, springs, atf leak, no key



<u>VEHICLE</u>	VEHICLE NUMBER	MILEAGE	<u>VIN</u>	INSPECTION STATUS	REPAIRS REQUIRED
2000 Ford F350 Pickup w/ EZ Dump w/pl	541	68,560	1FTWF33S4YED81955	WILL NOT PASS INSPECTION	Rust - frame rot, frozen shift cable, cab rockers, brake lines, torsion bar rods, transmission leak, rear axle seals, shocks, pinion seals, dump piston leak
2001 Dodge Ram 3500 Dump Truck	543	67,242	3B6MF36591M279259	WILL NOT PASS INSPECTION	Rust - cab & mounts, brake lines, front suspension, frame, gas tank & straps, exhaust, transfer case leak, shocks, battery
2001 Dodge Ram 2500 w/ Utility Bed	538	114,046	3B6KF26Z91M533802	WILL NOT PASS INSPECTION	Rust - rocker panels, brake lines, oil pan, cab floor, tires, battery
2003 Dodge Durango	617	225,587	1D4HS38N73F618371	WILL NOT PASS INSPECTION	Rust - drive shaft u joints, muffler, exhaust, pads, rotors, calipers, tires, trans leak, valve cover gaskets, exhaust manifold leak, broken bolts, inner tie rods alignment